

REPLACEMENT TILT/TRIM MOTORS & REPAIR KITS



DO NOT CUT WIRES OR DISMANTLE UNITS

Cutting a unit's wires or dismantling a unit immediately voids the manufacturer's warranty. Water can easily seep into the motor through cut wiring. In addition, taking a motor off the reservoir and trying to install it on an old reservoir usually damages the brushes in the motor. Disassembled parts are not covered by warranty.

6204 (NEW) O.E.M.
FITS: O.M.C.
3-wire connection
2 bolt mount

TR204
Repair kit



6206 (NEW) O.E.M.
FITS: O.M.C.
3-wire connection
3 bolt mount

TR206
Repair kit



6208 (NEW) O.E.M.
(MOTOR/RESERVOIR ONLY)
FITS: O.M.C. Outboards
3-wire connection

TR208
Repair kit



6209 (NEW) O.E.M.
FITS: O.M.C.
2-wire connection

TR209
Repair kit



6211 (NEW) O.E.M.
FITS: O.M.C. stern-drive
1979-1985 2.5L, 3.0L
3-wire connection
Ring Terminal Ends

TR211
Repair kit
(Cast Aluminum)

TR210
Repair kit
(Stamped Steel)





REPLACEMENT TILT/TRIM MOTORS & REPAIR KITS

6213 (NEW) O.E.M.
FITS: GOOD AUTOMATIC WINDLASS
 Ring Terminal Ends

Will also replace units with this style shaft



6217 (NEW) O.E.M.
(MOTOR/RESERVOIR ONLY)
FITS: B.M.W., MERCURISER, VOLVOPENTA
 Includes: Screws, gasket & adapter
 Ring Terminal Ends

TR217
 Repair kit



TAK217
 Screws, gasket, adapter



6214 (NEW) O.E.M.
MOTOR/RESERVOIR ONLY
FITS: O.M.C.
 1979-1985 3.8L,
 4.3L, 5.0L, 5.7L
 Stern Drive Engines
 2-wire connection



6218 (NEW) O.E.M.
(MOTOR ONLY)
FITS: MERCURISER I/O'S AND MERCURY OUTBOARDS W/OILDYNE PUMP
 12 Volt
 Ring Terminal Ends

Replaces early square-style motor

TR218
 Brush kit



6216 (NEW) O.E.M.
(MOTOR/RESERVOIR ONLY)
FITS: CHRYSLER, O.M.C.
 3-wire connection



6219
 Slow speed motor
 Fits Jack lift for racing outboards

6220 (NEW)
HEAVY-DUTY
FITS: O.M.C.
 2-wire connection
 Includes O-ring
 3 bolt mount
 Male Spade Terminal Ends

R473
 Relay available



REPLACEMENT TILT/TRIM MOTORS & REPAIR KITS



TR221 O.E.M.
(REPAIR KIT ONLY)
FITS: Discontinued
VOLVO PENTA Motor
897720-9



MOTOR IS NOT AVAILABLE

TR222 O.E.M.
(REPAIR KIT ONLY)
FITS: Discontinued
VOLVO PENTA Motor
Nos. 850046,
853520



MOTOR IS NOT AVAILABLE

6223 (NEW)
HEAVY-DUTY
FITS: VOLVO PENTA
Female Spade Terminal Ends

TR223 O.E.M.
Repair kit
Fits: Electrolux
motor only



This repair kit will not fit an ARCO heavy-duty motor!

6224 (NEW)
(COMPLETE)
FITS: VOLVO PENTA
Includes: Hydraulic valve body
Ring Terminal Ends

6225 (NEW) O.E.M.
(MOTOR/ RESERVOIR ONLY)
Fits: PRESTOLITE



← Replaces this style Prestolite Pump

6227 (NEW) O.E.M.
(COMPLETE)
FITS: VOLVO PENTA - THRU 1999
W/OILDYNE PUMP

6232
(MOTOR ONLY)



M531 (NEW)
RESERVOIR KIT
FITS: ARCO 6227
Includes: Reservoir,
cap, and O-ring

Fits Oildyne Pump ONLY

For new style 4 screw
mount see M533 in
miscellaneous section





REPLACEMENT TILT/TRIM MOTORS & REPAIR KITS

6228 (NEW) O.E.M.
HEAVY-DUTY
(MOTOR ONLY)
FITS: MANY SMALL
O.M.C. OUTBOARDS
Includes gasket



Fits: O.M.C. Pump
No. 173946



TR228

Repair kit



6231 (NEW) O.E.M.
(MOTOR ONLY)
FITS: U.S. MARINE
W/DILDYNE PUMP
2-wire connection
Female Spade Terminal Ends



To be discontinued when
present stock is exhausted

6232 (NEW) O.E.M.
(MOTOR ONLY)
FITS: ARCO 6227,
Late model VOLVO PENTA
W/ OILDYNE PUMP
2-wire connection



6238 (NEW)
HEAVY-DUTY
Fits: O.M.C.
1998-Up
75 HP-250 HP FFI
Outboard Engines
4 bolt mount,
Female Sealed
Terminal Ends
Includes O-ring



6239 (NEW)
HEAVY-DUTY
FITS: HONDA
1992-Up 35-50 HP
2-wire connection
Includes O-ring
4 bolt mount
Hollow-hex shaft
Female Spade Terminal Ends



6240 (NEW)
HEAVY-DUTY
FITS: YAMAHA
1997-UP 115 HP
2000-UP 115 HP 4-Stroke
1997-2000 130 HP
1997-UP 150-200 HP
1998-UP 225 HP
2-wire connection
4 bolt mount,
Ring Terminal Ends
Includes O-ring



© ARCO STARTING & CHARGING SPECIALISTS

Toll Free 800-722-2720 • Phone 850-455-5476 • Fax 850-453-2630 • www.arcomarine.com

REPLACEMENT TILT/TRIM MOTORS & REPAIR KITS



6241 (NEW)

HEAVY-DUTY

FITS: O.M.C. 60, 70, 90, 115, 150, 175 HP

1991-Up 200, 225 HP

1991-94 120, 140 HP

1995-Up 50 HP 3-cyl, 60 HP, V4 130 HP

1997-Up 115-200 HP

1998-99 225 HP

2-wire connection

4 bolt mount

Flat-blade shaft

Female Spade Terminal Ends



Includes O-ring and adaptor to replace motors with hollow hex shafts

ALSO REPLACES OEM MOTORS WITH HOLLOW HEX SHAFT

R473

Relay available



6244 (NEW)

HEAVY-DUTY

FITS: O.M.C.

1993 V6

1993-Up Commercial V8

2-wire connection;

3 bolt mount

Includes O-ring

Flat-blade shaft

Female Spade Terminal Ends



R473

Relay available



6245 (NEW)

HEAVY-DUTY

FITS: O.M.C. COBRA

1989-1993 Stern-drives (all models)

VOLVO 1994-Up 3.0-8.2L

2-wire connection; 3 bolt mount

Includes O-ring

Flat-blade shaft

Flag Connector Terminal Ends



6242 (NEW)

HEAVY-DUTY

FITS: O.M.C.

1992-Up J-suffix 40, 48, 50 HP

2-wire connection

Includes O-ring

4 bolt mount

Hollow-hex shaft

Female Spade Terminal Ends



R473

Relay available



6250 (NEW)

HEAVY-DUTY

FITS: Late model MERCURY

135, 150 XR6, Magnum III,

175, 200, 225, 250 HP,

105-140 HP Jet

2-wire connection; 2 bolt mount

Includes O-ring

Flat-blade shaft

Bullet Connector Terminal Ends



This motor will NOT replace an early model Mercury cartridge pump motor! Order Part No. 6278



6243 (NEW)

HEAVY-DUTY

FITS: O.M.C.

1989-1992 M-suffix 40,

48, 50 HP

2-wire connection; 4 bolt mount

Includes O-ring

Hollow-hex shaft

Male Spade Terminal Ends



R473

Relay available



6255 (NEW) O.E.M.

HEAVY-DUTY

FITS: Late model

MERCURY/FORCE

25-50 HP outboards

2-wire connection

4 bolt mount

Flat-blade shaft

Bullet Connector

Terminal Ends





REPLACEMENT TILT/TRIM MOTORS & REPAIR KITS

6260 (NEW)

HEAVY-DUTY

FITS: YAMAHA

1992-2002 90 HP

1992-1995 50-90 HP

1994 40 HP; 1996 70-90 HP

1997-Up 60, 70, 90 HP

3 bolt mount

2-wire connection,

Includes O-rings

Flat-blade shaft

Ring Terminal Ends



6268 (NEW)

FITS: SUZUKI

1991-1997 DT90,

1991-2000 DT100,

1991-2003 DT150,

1991-1992 DT175,

1991-2000 DT200,

1991-2003 DT225

3 bolt mount, 2-wire connection

Includes O-ring and adaptor

Ring Terminal Ends



6265 (NEW)

HEAVY-DUTY

FITS: YAMAHA

1987-1995

115-200 HP Outboards

1990-1994 225 HP

2-wire connection

3 bolt mount

Includes O-ring

Flat-blade shaft

Ring Terminal Ends



6269 (NEW)

FITS: SUZUKI DT 150/200

3 bolt mount

3-wire connection

Ring Terminal Ends



6270 (NEW) O.E.M.

(COMPLETE)

FITS: Late model MERCURY

225-275 HP Outboards w/Oildyne pump

Ring Terminal Ends



6266 (NEW)

FITS: YAMAHA

1995-Up 40/50 HP

2-wire connection

3 bolt mount

Ring Terminal Ends



6218 MOTOR ONLY

6274 (NEW)

HEAVY-DUTY

FITS: Late model MERCURY/MARINER & FORCE

75-125 HP outboards w/single ram

3-wire connection; 4 bolt mount

Hollow-hex shaft

(Motor/Reservoir Only for Trim Pump Assembly 824051)

Includes stainless steel mounting screws,

shaft adaptor, O-ring and fill plug.

Ring Terminal Ends

6267 (NEW)

FITS: YAMAHA

Early 70, 90, 115,

150-200 HP

3 bolt mount

3-wire connection

Ring Terminal Ends

4-mm thick shaft

blade with 68.3-mm

mounting collar.



© ARCO STARTING & CHARGING SPECIALISTS

Toll Free 800-722-2720 • Phone 850-455-5476 • Fax 850-453-2630 • www.arcomarine.com

REPLACEMENT TILT/TRIM MOTORS & REPAIR KITS



6275 (NEW) O.E.M. (COMPLETE)
FITS: Late model MERCURISER w/Dilydne pump
 Ring Terminal Ends



6218 MOTOR ONLY

M525 (NEW)
 Reservoir kit
FITS: ARCO 6275
 Includes: Reservoir, cap, O-ring, mounting screw



For new style 4 screw mount
 Mercruiser 883166A2 see M532
 in miscellaneous section

6276 (NEW)
HEAVY-DUTY
FITS: Late model MERCURY/MARINER, FORCE
 40-125 HP outboards w/single ram
 2-wire connection
 4 bolt mount
Hollow-hex shaft (Motor/Reservoir Only)
 Includes stainless steel mounting screws, shaft adaptor, O-ring and fill plug.
 Bullet Connector Terminal Ends



Will also replace these style units



6277 (NEW)
HEAVY-DUTY (MOTOR ONLY)
FITS: ARCO
 cartridge pump 6278 only!
 2 bolt mount
 Ring Terminal Ends



TR277
 Repair kit




Motor WILL NOT replace original equipment. Order Part No. 6278

6278 (NEW) (COMPLETE)
HIGH-PERFORMANCE
 Cartridge pump w/replaceable motor
FITS: MERCURY/MARINER
 35-220 HP Outboards
 2 bolt mount
 w/Design I, 3 ram,
 3 wire tilt/trim units
W/SIDE FILL RESERVOIR
 Replaces square-style Eaton,
 round-style Prestolite



TR277 SIDE FILL RESERVOIR
 Repair kit




6279 (NEW)
HEAVY-DUTY
FITS: MERCURY/MARINER
 outboards w/Design II
 3 ram, 3 wire trim units
 Hollow-hex shaft
W/AFT FILL RESERVOIR
 3-wire connection
 2 bolt mount
Shaft adaptor and O-ring included.
 Ring Terminal Ends



Replaces this square motor



AFT FILL RESERVOIR



TR279
 Repair kit



If you have questions about any of our products, please don't hesitate to call!
Toll Free 1-800-722-2720
1-850-455-5476

